

No. PB-1/ 1365/ of 2020

Office of The Deputy Executive Engineer,

Vapi (R & B) Sub Division,

Phone No. (0260) – 2401129

Vapi. Dtd. 24 /11/2020

To,

✓ The Managing Trustee,
Lumens Education Trust,
Lumens School,
S.No. 445, Near Panchayat Office,
At- Chandor, Ta. Vapi, Dist. Valsad


Subject :- Issue Building Stability Certificate.

Ref. :- Your office Letter Dtd. – 23.11.2020.

With reference to above cited subject, It is to inform you that by vide reference letter "Building Stability Certificate" is asked for Lumens School, S.No. 445, Near Panchayat Office, At- Chandor, Ta. Vapi, Dist. Valsad for Educational purpose.

The School Building (G + 1) was inspected by me on date 24.11.2020 and was certified by consultants. With reference to the certificate for the Stability of building given by Concept Designer & Engineering Consultants is found ok. This is for your kind information.

D.A. – Certificate


Deputy Executive Engineer
Vapi (R & B) Sub Division
Vapi

Copy submitted to Executive Engineer, Valsad (R & B) Division, Valsad for kindly information.


Certificate

This is to certify that the School Building (G + 1) was inspected by me on date 24.11.2020 and the certificate given by Concept Designer & Engineering Consultants for Lumens School, building is found in order.

Place :- Vapi

Date :- 24 /11 /2020




Deputy Executive Engineer
Vapi (R&B) Sub Division
Vapi